

GCA93

Giling Computer Applications

Fused current detector with fault indication

Revised: feb 27, 2012

Quantity	Reference	Part
8	R1 .. R8	33 Ohm
8	R9 .. R16	2K2
1	RP1	ARRAY 8 x 10K
8	GR1 .. GR8	B80C1500 rund (Reichelt)
2	U1,U2	LTV844 OR 2 x LTV824
1	J1	3 x AK012-03 (Reichelt)
8	F1 .. F8	PFRA 050 (Reichelt)
1	J3	PSS 254/10G (Reichelt)
8	D1 .. D8	DIODE 1N4148
8	Led1 .. Led8	LED red 3 mm red
8	Led9 .. Led16	LED 3mm high luminance (clear type)
1	connector	PSK254/10W
10	pins	PSK
4	support	M4x10
4	Screw	M4x8

GCA93

Giling Computer Applications

Fused current detector with fault indication

Revised: feb 27, 2012

Quantity	Reference	Part
8	R1 .. R8	33 Ohm
8	R9 .. R16	2K2
1	RP1	ARRAY 8 x 10K
8	GR1 .. GR8	B80C1500 rund (Reichelt)
2	U1,U2	LTV844 OR 2 x LTV824
1	J1	3 x AK012-03 (Reichelt)
8	F1 .. F8	PFRA 050 (Reichelt)
1	J3	PSS 254/10G (Reichelt)
8	D1 .. D8	DIODE 1N4148
8	Led1 .. Led8	LED red 3 mm red
8	Led9 .. Led16	LED 3mm high luminance (clear type)
1	connector	PSK254/10W
10	pins	PSK
4	support	M4x10
4	Screw	M4x8